




GENESIS™ KIOSK PLINTH TRIM KIT INSTRUCTIONS




KIT CONTENTS

- ITEM 1 - Side Panel x 2
- ITEM 2 - Front Panel x 2
- ITEM 3 - Screw and Caps x 16
- ITEM 4 - Corner Brackets x 4



EQUIPMENT REQUIRED

- Power Drill
- Pozidriv Drill Bit




1

2



3




4


DIAGRAMS NOT TO SCALE

INSTALLATION INSTRUCTIONS


1. Position panels against their corresponding length wall.




2. Ensure panels are positioned as shown.




3. Place Corner bracket over the ends of the boards.



4. Using a power drill and Phillips head, drill in the screws through the brackets into the panels and close the caps.




5. Repeat this process for the remaining 3 corner brackets on each corner.



IMPORTANT NOTE: PLEASE ENSURE THAT ALL RELEVANT PERSONNEL READ THE POINTS LISTED WITHIN THIS LEAFLET AND THAT A COPY IS GIVEN TO STAFF INVOLVED WITH THE INSTALLATION AND MAINTENANCE OF THIS PRODUCT

SAFETY NOTE: PLEASE REFER TO 'THE MANUAL HANDLING OPERATIONS REGULATIONS 1992' DURING HANDLING.

 **Glasdon** AND LUMINO CITY ARE TRADEMARKS OR REGISTERED TRADEMARKS OF GLASDON GROUP OR ITS SUBSIDIARIES IN THE U.K AND OTHER COUNTRIES

• A planned maintenance schedule or regular inspection is recommended, replacing components as necessary.

• Replacement components are available direct from GLASDON.

• GLASDON cannot be held responsible for claims arising from incorrect installation, unauthorised modifications or misuse of the product.

Issue 1 - September 2015 - Stock No. C000/0483 - DWG No. 12B-088-17
© Copyright 06/2013

Glasdon UK Ltd reserve the right to alter specifications without prior notice.



Glasdon U.K Limited

Preston New Road
BLACKPOOL
Lancashire FY4 4UL
Tel: 01253 600410
Fax: 01253 792558
email: sales@glasdon-uk.co.uk
web: www.glasdon.com